


Photographs and Descriptions



Photograph No. 1. Looking north at south elevation.




Photograph No. 2. Looking east at west elevation showing infilled windows, brick spalling, and missing bricks and mortar.

Photographs and Descriptions - continued



Photograph No. 3. Looking south at north elevation, including cut back section.



Photograph No. 4. Looking west at south portion of east elevation.

Photographs and Descriptions - continued



Photograph No. 5. Looking south at roof from north end. Not detached roofing and lack of parapet cap along east wall.



Photograph No. 6. Looking west at low spot in roof where roof drain connects. Note loose and disconnected roofing.

Photographs and Descriptions - continued



Photograph No. 7. Looking west at north end of roof. Note bare roof sheathing.



Photograph No. 8. Collapsed bay at first floor. Note sagging floor joists.

Photographs and Descriptions - continued



Photograph No. 9. Looking up along south side of collapsed bay.



Photograph No. 10. Showing sagging floor at fourth floor level.

Photographs and Descriptions - continued



Photograph No. 11. Looking south along west wall, showing sagging at fifth floor level.



Photograph No. 12. Showing first floor framing from the basement. Note arched concrete in foreground and water stained joists in background.

Photographs and Descriptions - continued



Photograph No. 13. Looking south along center bay. Note first floor water damage and water staining to second floor joists.



Photograph No. 14. Showing typical water staining to joists and decking.

Photographs and Descriptions - continued



Photograph No. 15. Looking at second floor from below showing holes through deck.




Photograph No. 16. Fifth floor showing deteriorated decking, particularly in the center bay.

Photographs and Descriptions - continued



Photograph No. 17. Showing broken fourth floor joists near center of center bay.



Photograph No. 18. Showing broken fourth floor joists near center of center bay.

Photographs and Descriptions - continued



Photograph No. 19. Showing fifth floor ceiling joists and newer timber roof trusses.



Photograph No. 20. Looking at bottom of access door in sidewalk from vault south of south elevation of building. Concrete beam to left supports the south wall.